

Atlanta Airport Daily Report

Day Saturday
Date 2/7/2026

Management @ Site			
Name	Position	Phone	Email
Jerald Mitchell	General Manager	771-210-1255	gerald.mitchell@versar.com
Cruz Santiago	Compliance Manager	470-336-9922	Cruz.Santiago@versar.com
Sammy Exantus	Facility Manager	771-210-1452	sammy.exantus@versar.com

Weather Conditions							
AM Weather	Wind (MPH)	Dew Pt. (F)	Humidity (%)	PM Weather	Wind (MPH)	Dew Pt. (F)	Humidity (%)
	14				9		
Precipitation		AM	PM	Weather Delay	None	Temp Max (F)	Temp Min (F)
Describe Conditions		Windy, up to 14mph.					

Hours Onsite				
Versar Team Member		Contractor		
Name	Hrs. On site	Company Name	Resource Name	Hrs. On site
Jerald Mitchell	12	Environmental Restoration	OSRO	12
		BASHA Services, LLC	OSRO	24
		Southern Petroleum	OSRO	0
Total Hrs.	12		Total Hrs.	36

Summary of Day's Activities
Continued collection at most impacted areas, AATC and Upper Riverdale. Maintenance work and maintaining progress at Forest Pkwy, Lee's Mill Rd., and Valley Hill Rd. This means quick recovery of sediment collection and boom replacement as needed.

Atlanta Airport Daily Report Outfall FR-1/AATC

Day Saturday
Date 2/7/2026

Activity Log	
Planned Daily Activities Description	
Due to the shift in the wind the fuel has moved into a pocket, still within boomed area. Skimmers repositioned.	
Activity	Comments
A - Containment booms deployed and checked (provide status)	Checked daily and exchanged as needed
B - Vac truck recovery operations scheduled or underway	4
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	Only hoses
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	Constantly Changing
G - Sheen visibility approx. area	Constantly Changing
Start of Day Photos	
End of Day Photos	
Photos	Comments
New or Continued Issues Encountered	
Lab Results Summary	n/a
Lab Result Report Number	n/a



Atlanta Airport Daily Report Forest Parkway

Day Saturday
Date 2/7/2026

Activity Log	
Planned Daily Activities Description	
e mode - manual collection. Overnight debris and scum has made its way down, this is being collected manually	
Activity	Comments
A - Containment booms deployed and checked (provide status)	Checked this morning, will change this evening
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	Capturing all at end of day
G - Sheen visibility approx. area	Constantly changing
Start of Day Photos	
End of Day Photos	
Photos	Comments
New or Continued Issues Encountered	
Lab Results Summary	n/a
Lab Result Report Number	n/a

Atlanta Airport Daily Report Lee's Mill Rd

Day Saturday
Date 2/7/2026

Activity Log	
Planned Daily Activities Description	
Manual collection of debris. Some debris has made its way downstream and is being collected this morning.	
Activity	Comments
A - Containment booms deployed and checked (provide status)	Checked daily and exchanged as needed
B - Vac truck recovery operations scheduled or underway	1 truck
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	Capturing everything at the end of day as it makes its way downstream
G - Sheen visibility approx. area	Minimal - however constantly changing
Start of Day Photos	
End of Day Photos	
Photos	Comments
New or Continued Issues Encountered	
Lab Results Summary	n/a
Lab Result Report Number	n/a

Atlanta Airport Daily Report Upper Riverdale Rd

Day Saturday
Date 2/7/2026

Activity Log	
Planned Daily Activities Description	
The boat is in the water. 200 bags of litter and debris collected, to be disposed in a roll-off. Contaminated and covered limbs and branches are collected on the river bank for disposal into the roll-off bin.	
Activity	Comments
A - Containment booms deployed and checked (provide status)	Hard and soft booms coraling debris to the north side of the bridge. Frequently changed out.
B - Vac truck recovery operations scheduled or underway	1
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	Work in progress
G - Sheen visibility approx. area	Constantly changing
Start of Day Photos	
End of Day Photos	  
Photos	Comments
Lab Results Summary	n/a
Lab Result Report Number	n/a

Atlanta Airport Daily Report Valley Hill Rd

Day Saturday

Date 2/7/2026

Activity Log

Planned Daily Activities Description

Maintenance work

Activity	Comments
A - Containment booms deployed and checked (provide status)	Checked daily and exchanged as needed
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	Cleaning any residual
G - Sheen visibility approx. area	None

Start of Day Photos



End of Day Photos



Photos	Comments
New or Continued Issues Encountered	
Lab Results Summary	n/a
Lab Result Report Number	n/a

Atlanta Airport Daily Report Rock Quarry

Day Saturday
Date 2/7/2026

Activity Log	
Planned Daily Activities Description	
Maintenance work	
Activity	Comments
A - Containment booms deployed and checked (provide status)	Checked daily and exchanged as needed
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 9th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	n/a
F - Percentage of collection	90%
G - Sheen visibility approx. area	Minimal
Start of Day Photos	
End of Day Photos	
Photos	Comments
New or Continued Issues Encountered	
Lab Results Summary	n/a
Lab Result Report Number	n/a
Lab Result Report Number	n/a