



Atlanta Airport Daily Report

Day Wednesday
Date 2/11/2026

VGS2M JOINT VENTURE

Management @ Site

Name	Position	Phone	Email
Jerald Mitchell	VGS2M General Manager	771-210-1255	gerald.mitchell@versar.com
Cruz Santiago	VGS2M Compliance Manager	470-336-9922	Cruz.Santiago@versar.com
Sammy Exantus	VGS2M Facility Manager	771-210-1452	sammy.exantus@versar.com
Justin Deadwyler	VGS2M Program Manager	470-702-2109	justin@2mnext.com
Nia Thomas	Corporate QHSE	240-252-2304	Nia.Thomas@versar.com

Weather Conditions

AM Weather	Wind (MPH)	Dew Pt. (F)	Humidity (%)	PM Weather	Wind (MPH)	Dew Pt. (F)	Humidity (%)	
	4	44	86		13	52	49	
Precipitation	AM	PM	Weather Delay	None	Temp Max (F)	Temp Min (F)		
					67	48		
Describe Conditions								

Hours Onsite

VGS2M Resources		Contractor			
Name	Hrs. On site	Company Name	Resource Name	Hrs. On site	
Cruz Santiago	8	Environmental Restoration	OSRO	12	
Jerald Mitchell	12	BASHA Services, LLC	OSRO	8	
Nia Thomas	8				
Sammy Exantus	8				
Justin Deadwyler	8				
Total Hrs.	44		Total Hrs.	8	

Daily Summary

- 1.) Overlays of Jet-A and water samples from 2/2 & 2/9 have been returned. Water sample results from 2/9 have also been returned.
- 2.) With incoming rain, the southernmost remediation area, Valley Hill, was reinforced with additional soft booms. A skidder was brought on site to remove contaminated vegetation from the banks of Upper Riverdale Rd.
- 3.) Current Solid Waste: > 3 x 20 yard containers. Ordering a 4th container.
- 4.) At the end of the day the tank was measured and determined to be ~567 gal of fuel, ~4536gal of water. The tanks were not full and therefore not emptied.

Total Volume of Fuel Collected: NOTE: these are approximate figures and are subject to change. Total fuel volume was determined using manual tank gauging in the field with fuel-finding paste when the tanks are full. The frac tanks are positioned on an approximate one-foot incline, which may distort the calculated total volume. More accurate figures will be determined at the point of disposal.

Fuel Recovered

Date	Volume	Date	Volume	Date	Volume	Date	Volume
2-Feb	2520	5-Feb	Tanks not full	8-Feb	Tanks not full	11-Feb	Tanks not full
3-Feb	3608	6-Feb		9-Feb	5270	12-Feb	
4-Feb	2452	7-Feb		10-Feb	1330	13-Feb	
						Total	15180

PCW Volume

Date	Volume	Date	Volume	Date	Volume	Date	Volume
2-Feb	11760	5-Feb	Tanks not full	8-Feb	Tanks not full	11-Feb	tanks not full
3-Feb	8525	6-Feb		9-Feb	21508	12-Feb	
4-Feb	7104	7-Feb		10-Feb	9230	13-Feb	
						Total	58127



Atlanta Airport Daily Report Outfall FR-1/AATC (Site 2)

Day	Wednesday
Date	2/11/2026

Activity Log

Planned Daily Activities Description

4 vac trucks total collecting scum and oil from the surface, using the boat and blowers to section off area.

Activity	Comments
A - Containment booms deployed and checked (provide status)	Exchanged
B - Vac truck recovery operations scheduled or underway	4
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	Pool skimmers
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	60%-70%
G - Sheen visibility approx. area	500-1000 sq. ft.

Start of Day Photos	
---------------------	--

End of Day Photos	
-------------------	---

Photos	Comments
New or Continued Issues Encountered	

Atlanta Airport Daily Report Forest Parkway (Site 3)

Day Wednesday
Date 2/11/2026

Activity Log

Planned Daily Activities Description

Collecting residuals from the top of the water.

Activity	Comments
A - Containment booms deployed and checked (provide status)	Exchanged
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	~80%
G - Sheen visibility approx. area	50 sq. ft.

Start of Day Photos	
---------------------	---

End of Day Photos	
-------------------	--

Photos	Comments
New or Continued Issues Encountered	The water looks foamy.



Atlanta Airport Daily Report Lee's Mill Rd (Site 4)

Day	Wednesday
Date	2/11/2026

Activity Log

Planned Daily Activities Description

Small crew manually removing oil from the top of the surface using pads.

Activity	Comments
A - Containment booms deployed and checked (provide status)	Exchanged
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	Almost complete. Maintenance work with top scum that migrates overnight.
G - Sheen visibility approx. area	50 sq. ft.

Start of Day Photos	
---------------------	--

End of Day Photos	
-------------------	--

Photos	Comments

Atlanta Airport Daily Report Upper Riverdale Rd (Site 5)

Day Wednesday
Date 2/11/2026

Activity Log

Planned Daily Activities Description

Collecting vegetation from the river and the banks. Manual collection of top scum.

Activity	Comments
A - Containment booms deployed and checked (provide status)	Maintained
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	Progressing
G - Sheen visibility approx. area	200-500 sq. ft.

Start of Day Photos	 
---------------------	--

End of Day Photos	
-------------------	--

Photos	Comments
	Back hoe and skid trucks used to remove contaminated vegetation



Atlanta Airport Daily Report Valley Hill Rd (Site 6)

Day	Wednesday
Date	2/11/2026

Activity Log

Planned Daily Activities Description

Added new soft booms in anticipation of the heavy rain.

Activity	Comments
A - Containment booms deployed and checked (provide status)	Maintained
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	80%
G - Sheen visibility approx. area	<25sqft

Start of Day Photos

End of Day Photos



Photos

Comments

New or Continued Issues Encountered

Atlanta Airport Daily Report Rock Quarry (Site 1)

Day	Wednesday
Date	2/11/2026

Activity Log

Planned Daily Activities Description

Activity	Comments
A - Containment booms deployed and checked (provide status)	n/a
B - Vac truck recovery operations scheduled or underway	n/a
C - Water Samples non-scheduled or to be taken	Monday, February 16th
D - Skimmers being utilized	n/a
E - Water Samples status with lab (sent/scheduled return, etc.)	Returned
F - Percentage of collection	Near total
G - Sheen visibility approx. area	None

Start of Day Photos



End of Day Photos

Photos

Comments

New or Continued Issues Encountered